

To: Dadap, Nathan C. [DADAP.NATHAN@EPA.GOV]
Cc: Santos, Carmen [Santos.Carmen@epa.gov]; Beach, John [Beach.John@epa.gov]
From: Conlan, Linda
Sent: Fri 5/15/2015 10:27:51 PM
Subject: RE: Follow-up to yesterday's Pechiney call

Thank you!

Linda Conlan, PG
Principal Geologist
Amec Foster Wheeler
Environment & Infrastructure, Inc.

From: Dadap, Nathan C. [mailto:DADAP.NATHAN@EPA.GOV]
Sent: Friday, May 15, 2015 2:59 PM
To: Conlan, Linda
Cc: Santos, Carmen; Beach, John
Subject: Follow-up to yesterday's Pechiney call

Linda,

It was great to speak with you yesterday. We really appreciate your help in facilitating the review process. I'm following up to document some of the deliverables that we discussed, as well as provide you with those sample locations/IDs in Figure 6 which seemed to contain potential errors during spot checks.

1. In summary, the **figures** we discussed that AMEC would submit to EPA will depict the following:

PCB samples only, in soils only, with a grid overlay and color-coding (to help identify which sample concentrations above the cleanup level) for -

- Pre-underground demolition samples
- All post-demolition samples 0-5 ft
- All post-demolition samples 5-15 ft
- All post-demolition samples 15+ ft
- Only samples remaining in place

Please let me know if there's anything there that doesn't sound correct. We also are requesting the full data table of PCB samples in soil (including those that were excavated) to help identify those locations which exceeded the cleanup level. As you had mentioned, there would be a column to denote whether the sample was Left behind (L), a Verification sample (V), was a verification sample but was excavated (V/E), or excavated (E).

2. In spot-checking Figure 6 of the final report, we found some potential errors in the figure:

Sample locations which did not have an ID
Phase IV – the boring about 10 feet north of #849

Sample IDs that did not point to a boring
Phase I – 208-SS-005
Phase IV – 56-SS-009, SWC-3, 563-SS-008

Verification samples where the boundary of excavation appears to envelope the sample location
Phase I – 32-SS-025, 27, and 29; #629

Samples on the figure that were not in the data table – (these may not have been considered verification samples and thus not included)
Phase I – the 274-SS samples near Concrete Removal Area N
Phase IIA - #713, #710, 251-SS-001, and 605-SS-002 near Concrete Removal Area C; #1257; the samples around and including #1266
Phase IIIA – 293-SS-008, 293-SS-002, 293-SS-003
Phase IV – #1124

Thanks again and have a nice weekend.

Nathan

Nathan Dadap
U.S. EPA Region 9
RCRA Facilities Management
75 Hawthorne Street
San Francisco, CA 94105

Phone: (415) 972-3654

Fax: (415) 972-3530



This message is the property of Amec Foster Wheeler plc and/or its subsidiaries and/or affiliates and is intended only for the named recipient(s). Its contents (including any attachments) may be confidential, legally privileged or otherwise protected from disclosure by law. Unauthorised use, copying, distribution or disclosure of any of it may be unlawful and is strictly prohibited. We assume no responsibility to persons other than the intended named recipient(s) and do not accept liability for any errors or omissions which are a result of email transmission. If you have received this message in error, please notify us immediately by reply email to the sender and confirm that the original message and any attachments and copies have been destroyed and deleted from your system. This disclaimer applies to any and all messages originating from us and set out above. For Canada and the United States: If you believe this is an unsolicited email and do not wish to receive future commercial electronic messages from us, please click unsubscribe@amecfw.com and include "Unsubscribe" in the subject line.

Please click <http://amecfw.com/email-disclaimer> for notices and company information in relation to emails originating in the UK, Italy or France.